



**Borealis Mining Company LLC**  
12 Miles SW of Hawthorne on Lucky Boy Pass Road  
Hawthorne, NV 89415

**POSITION DETAILS**

<b>Position Title:</b>	<b>Maintenance Millwright</b>
<b>Department:</b>	<b>Production</b>
<b>Location:</b>	<b>Borealis Mine Site</b>
<b>Reports to:</b>	<b>Process General Foreman</b>

**Basic Function:** The Maintenance millwright will be responsible for maintaining and repairing all process equipment and machinery while optimizing processing and reducing equipment downtime by performing predictive and preventative maintenance on all equipment and machinery.

**Duties and Responsibilities:**

- Mechanical repair and installation of process equipment, Goulds and Wemco Hidrostral pumps and screens.
- Perform preventative and predictive maintenance procedures; greasing, oiling, changing filters, equipment inspections, etc.
- Capable of welding, cutting, grinding, and fabrication.
- Complete work orders and other maintenance documentation.
- Perform housekeeping duties and work area checks.
- Trouble shoot equipment and determine root cause analysis.
- Attendance is deemed an essential job function.

**Qualifications:**

- 1-2 years of welding; stick and wire feed, vertical, horizontal, overhead; and fabricating experience.
- Ability to rebuild pumps, perform dial and/or laser alignment, install mechanical seals and couplers.
- Ability to operate a variety of light equipment, hand trucks, forklift, and vehicles.
- High school diploma or equivalent.

**Physical Demands:**

- Personal protective equipment is required when performing work in a mine, outdoor, manufacturing or plant environment, including hard hat, hearing protection, safety glasses, safety footwear, and as needed; respirator, rubber steel-toe boots, protective clothing, gloves and any other protective equipment as required.
- Employee is occasionally required to crawl, kneel, bend, and reach with hands and arms above their shoulders.
- Must be able to lift and carry up to 30-50lbs
- Ability to work in extreme weather conditions; exposure to wet and/or humid outside weather conditions; and extreme cold and/or heat.
- Ability to maintain awareness of occupational hazards and safety precautions. Skilled in following safety practices and recognizing hazards.
- Physically capable of sitting or standing, shovelling and performing other types of physical work for long periods of time.
- Must be willing to work shift work or otherwise assigned.
- Must be a self-starter.

Supervisor's Signature with date: _____ Job Holder's Signature with date : _____